

TX-RZ70 – Current Firmware Update Notes (3 Mar 2026)

Update History

Current Version R124-0708-1133-0134

The 3 Mar 2026 update will address the following:

1. Updated Chromecast version.
2. Fixed an issue where files containing the character “\$” in tag information could not be played.
3. Fixed an issue where playback of DSD (DSF) files stopped unexpectedly.
4. Improved speaker S/N(signal-to-noise) performance during DLBC/DLBM operation.

The 1 Jul 2025 update will address the following:

1. Support for Spotify Lossless. (Added in November 2025)
2. Fix an issue where the DLBC(Dirac Live Base Control)/DLBM(Dirac Live Base Management) crossover was applied incorrectly.
After applying the update, please re-export/transfer the filter(target EQ) to each slot.
3. Minor bug fixes and improvements stability.
4. Add setup microphone switching procedure.
For details, please refer here.
https://assets.onkyo-av.com/product-firmware/Switching-the-Setup-Microphone_OI.pdf

The 12 Mar 2025 update will address the following:

1. Minor bug fixes and improvements stability.

The 18 Nov 2024 update will address the following:

1. Google Cast2.0
For details, please refer here.
https://assets.onkyo-av.com/product-manuals/supple_cast20_onk.pdf
2. Support Tidal MAX
3. Improve the Dirac Live measurement on the Onkyo Application.
4. Minor bug fixes and improvements stability.

The 23 Apr 2024 update will address the following:

1. Minor bug fixes and improvements stability.

The 4 Dec 2023 update will address the following:

1. Roon Ready
update from Roon Tested
2. Adding Pre amp mode

The 5 Sep 2023 update will address the following:

1. Add Auro 3D function
Please refer to the link below for more details.
<https://www.onkyo.com/manual/sup/upd/auro.pdf>
2. Add SBTM(Source Based Tone Mapping) of HDMI2.1a.
3. Dolby Atmos Music playback capability of Amazon Music HD.
4. Add 4 Klipsch Reference Premiere Subwoofer for Klipsch Optimized mode.
RP-1000SW
RP-1200SW
RP-1400SW
RP-1600SW
5. Raise the upper limit of the Dirac delay time from 20 msec to 50 msec.
6. Fix the issue of displaying messages related to OSD signals when connecting the Optoma projector.
7. Fix the issue where enabling Bluetooth transmission would prevent HLG display.
8. Minor bug fixes and improvements stability.

Update instructions

Update the firmware via network or USB connection.

- "Updating the firmware via network"
You can update the firmware by connecting the unit to a network.
- "Updating the firmware via USB connection"
You need a 128 MB or larger capacity USB storage for updating.

For details, see "Firmware Update" of the Instruction Manual.

GNU GPL/LGPL-applicable Software

Please refer to the following link for the Copyright Notice of GNU GPL/LGPL-applicable Software.

https://assets.onkyo-av.com/product-firmware/OSS_2019AVR.pdf